SFUND RECORDS CTR 2072087

Timex Corporation

File No. 2189.8156

Summary: Timex Corporation operated a liquid crystal products manufacturing facility at 20650 Valley Green Drive in Cupertino, California between 1978 and 1983. A 500 gallon capacity fiberglass waste chemical storage tank was removed in 1983 and soil samples were collected and anaylzed. None of the solvents used at the facility were detected in the samples. However, the presence of 2-2-oxybisethanol (diethylene glycol) in concentrations from 1180 ppb to 13,000 ppb were found. Subsequent soil sampling and anaylses found no detectable levels of the diethylene glycol. The tank and some soils were excavated and removed from the site.

Recommendation: Considering that this site poses no apparent threat to surface or groundwaters of the State, no further action is recommended in this matter. A letter stating this fact will be sent to Timex Corporation in January, 1987 from the Regional Water Quality Control Board.

taken where the tank was do not the contain hazardous wastes. The absence of hazardous waste suggests that this site is not a threat to the surface or groundwater. Therefore, no further action under CERCLA is recommended.

Holly Hadlock

Jhere does not appear to be an uncontrolled hayardors worte problem here Not further action evel Cerela appears warrental.

2.17.87

### Region 9

File No. 2189.8156

Preparer's Name Ronald H. Clawson (415) 464-0825 Date December 23, 1986

Steven Inn (415) 444-0837

3 6	even Inn (413	
<u> </u>	SOURCE	INFORMATION
1. Site ID Number		
2. Site Name		Timex Corporation
3. Site Location		20650 Valley Green Drive Cupertino, CA 95014
4. County		Santa Clara
5. Owner (Address & telephone no.)	12/8/86 telephone conversation	Sobrato Development Companies 10600 N. De Anza Blvd. Suite 200 Cupertino, CA 95014 Attn: Nancy Williams (408) 446-0700
6.** Operator (Address & telephone no.)	"	Timex Corporation 20650 Valley Green Drive Cupertino, CA 95014 (408) 249-6965 (until 1983)
7. Type of Ownership	11	Private
B. Status	"	Inactive - Tank removed
9. Source Activity		Various solvents were used in the process of manufacturing liquid crystal products. Waste solvent was placed into a 600 gal. buried fiberglass tank.
10. Years of Operation	12/8/86 tele. con.	1978 to 1983
11. Facility Type		y Waste solvents dumped into a buried 600 gal. capacity tank.
12. Waste Type and Description	"	Hexanes, ispropyl alcohol, ethanol, methanol, benzene, toluene, acetone. None of these were found in the soil under the excavated tank.

#### EPA-IX-FORM 890

.1/18/83

4.	Incidents	
	Fire and Explosion NO Direct Contact NO	£ 7).
15.	Inspections (date, type, by whom, recommendations) NONE	
	-	عداد بعدان المعار
16.	Enforcement History (list date, type of action, reoutcome) NONE	equirements,
16.	outcome)	equirements,
17.	outcome)	
17.	NONE  a. Initial recommendation for further action:  No further action is recommended since the site poses no threat	





#### SAFETY SPECIALISTS, Inc.

3284F Edward Avenue, Santa Clara, California 95050 • Telephone (408) 988-1111 Mailing Address: P.O. Box 4420, Santa Clara, CA 95054

December 9, 1983

Mr. Steven R. Ritchie
Associate WRCE
California Regional Water
Quality Control Board
San Francisco Bay Region
1111 Jackson Street, Room 6040
Oakland, CA 94607

CALIFORNIA REGIONAL WATER

DEC 12 1983

QUALITY CONTROL BOARD

Dear Mr. Ritchie:

The following is our operations plan for the removal and disposal of a 600-gallon waste storage tank belonging to Timex Corporation.

- I. Tank location
  - A. 20650 Valley Green Drive Cupertino, California 95014
  - B. See Site Plan for tank location within facility.
- II. Tank construction
  - A. Fiberglass tank (600-gallon)
  - B. Iron piping
  - C. Installed 1978
- III. Previous tank use

Waste flammable solvents

- A. Hexanes
- B. Isopropyl alcohol
- C. Ethanol
- D. Methanol
- E. Benzene
- F. Toluene
- G. Acetone

#### IV. Safety precautions

- A. Supervision by a safety professional
- .B. Isolation from all ignition sources
- C. Tank empty and inert
- D. Lines flushed and capped

#### V. Removal procedures

- A. Isolate from all ignition sources
- B. Empty tank
- C. Flush lines with detergent and water
- D. Solidify residue
- E. Inert tank and lines
  - 1. CO2 for lines
  - 2. Dry ice (9 lbs) for tank
- F. Cap all openings except vent pipe
- G. Wait one hour for oxygen and vapor displacement, test with GasTech
- H. Begin excavation to expose tank and pipe lines
- I. Remove pipe lines and cap or plug all openings leaving a 1/8-inch pressure relief hole at top of tank
- J. Inspect all joints and connections to tank for leakage. If leakage is suspected, sample soil below joints on connection. Refrigerate samples and transport to laboratory.
- K. Remove tank
- L. Inspect tank for integrity
- M. Seal any holes
- N. Remove soil samples from area below tank at depths of 2 and 4 feet. If leakage found, sample area below leak.
- Refrigerate samples and transport to laboratory



#### Mr. Steven R. Ritchie

3

- P. If no contamination found, back-fill excavation
- Q. If contamination found or suspected, seal site, contact California Regional Water Quality Control Board and prepare site mitigation plan
- R. Properly load, secure, manifest, and transport tank to a Class I disposal site

Copies of all test results shall be sent to the California Water Quality Control Board.

If you have any questions or need further information, please feel free to call me at 408-995-6344.

Sincerely,


SAFETY SPECIALISTS, INC.

Michael L. Borden

President

MLB:wlm

Enclosure



# SAN FRANCISCO BAY REGION

**INTERNAL MEMO** 

TO:	FROM:
DATE: December 11,1986	SIGNATURE: Meren In
SUBJECT: Questions of Safety &	
Those call to youssel of	C- Sloubary at (408) 988-1111
In on , a number of ion	mounds detected in the soil
sample are reported to be o	products of coal tas commonly
Used in asphalt pavemen	t. Why would a sample
collected at 20 H. pick	up a piece of acphalt?
youssel englained that BH.	
of the area backfilled after	
been excavated. The ma	
<b>→</b>	The absence of these compounds
in the other bour samples o	on the perimeter of the executed
area further show that these	compounds are not a result of
tank ledkøge.	•
In regards to the 1,1'- o	aybisoctane reported in one
sample in the Tebruary 1	984 report, the compound
is closely related to diethy	dene glycol, 2,2-caylisethand.
This compound was not a	detected in the recent campling
mentioned above.	·
	•

SWRCB 326A (4/75)

## SANFRANCISCO BAY REGION

**INTERNAL MEMO** 

TO: File	#2189.8156	FROM:	SOI	
DATE:	ember 8, 1986	SIGNATURE:	Steven Inn	
	History on Tim			÷
Pho	ne call to Tom	Thinesen of	Times (408) 249-6	865
· Tacelety De	escription			
Light man	nufactures of liquid	crystals for a	vatches	
year of Op	ention	•		
1978 to	December 1983			
Tom sai	I he believes App nt of the bacility	de Computers	is the current	
остран	nt of the facility	. During	the years of	
operation	, Times lease	ed the ongo	serty from:	
ngari Marana	Soberto De		_	
	10600 Plost	& De any	Alvd., Suit 20	-c
	Cypertino,			
	(408) 446.	0700	:	
	Contact	Dancy Willes	i.	

SWRCB 326A (4/75)

SURNAME:

### SANFRANCISCO BAY REGION

**INTERNAL MEMO** 

TO:
DATE: Desember 8, 1886 SIGNATURE: Steven him
SUBJECT: Current information on Timer's former cite
in Cupertino.
. Show call to Debbie Gerez of Agale Computer,
Real Estate Department. (408) 973-5032
Apple Computers, Inc. is the occupant at
20650 Valley Brean Drive in Capertono.
They began operations in January of 1984,
The owner of the susperty is:
Sobrate Development Companies
10600 North De Anga Blad., faite 200
Cupertino, CA 95014
(408) 446-0700
Contact: Nany Williams

SWRCB 326A (4/75)

til skilling of the

**SURNAME:**